

NORTHEAST AERO DER APPROVED IN-HOUSE REPAIRS

REPAIR P/N	REPAIR Description	NHA P/N	NHA Description	OEM	A/C Application	Scope of Repair
NAS1802-5D-17	Bolt	810209-x	Air Cycle Machine	Hamilton	B-777	Bolt Retention
810209-102	Retaining Plates	810209-x	Air Cycle Machine	Hamilton	B-777	Plate Retention
3177942-1	Valve Body	3215302-x	Shutoff Valve	Honeywell	B-777-200	Restore surface treatment
1043V0109	Seal	1043V0300	Bypass Valve	Honeywell	B757-200, PW2037	Seal Assembly
3238782-1	Seal	3505854-x	Air Turbine Gearbox	Honeywell	B-777-200	Radial Seal
1501-210	Locating Pin	1U1501-4	Isolation Valve	Woodward	777-200, 777-300, 777F	Worn Pin
3504821-1	Spacer	3505854-x	Air Turbine Gearbox	Honeywell	B-777-200	Worn Spacers
AC031051	Bush Valve Seals	AC67352, AC67740, AC67732	MKIII BRAKE CONTROL VALVE	Meggitt	BH/DH/HS.12 5 Series	Worn Seals
AC041481	Valve Seat	AC65216, AC65218	Axel Mounted Maxaret	Meggitt	BH/DH/HS.12 5 Series	Worn Seat
3501787-1	Mounting Rod	3268792-x	Air Turbine Driven Pump Assembly	Honeywell	B-767-300, B-767	Damaged Threads
1211292-xxx	Main Housing	1211342-x	Actuator, Variable Stator	GE (Arkwin)	A330, B747, B767, CF6	Worn Mount

NORTHEAST AERO DER APPROVED IN-HOUSE REPAIRS

REPAIR P/N	REPAIR Description	NHA P/N	NHA Description	OEM	A/C Application	Scope of Repair
330751	Housing	421865-x	Thermal Anti-Ice Valve	Whittaker	ERJ170/175/ 190/195	Worn Sleeves
3177057-1	Valve Body	3215394-x	Modulating Shut-Off Valve	Honeywell	B-777-200	Restore surface treatment
3958A0000-01	Valve Body	3958A0600-x	Bypass Valve	Liebherr	A318,A319,A 320,A321	Main bore
1380325-8/-9/-10	Shims	1380209-x	Air Cycle Machine	Hamilton	A380	Alternate Repair Process
1380324-7	Shims	1380209-x	Air Cycle Machine	Hamilton	A380	Alternate Repair Process
1380327-7/-8	Shims	1380209-x	Air Cycle Machine	Hamilton	A380	Alternate Repair Process
1380328-7/-8	Shims	1380209-x	Air Cycle Machine	Hamilton	A380	Alternate Repair Process
7206787-1	Sleeve	3215302-x	HPPSSV	Honeywell	B-777-200	Bearing Sleeve
1001233-1	Tie Rod Support	1000700-x	Air Cycle Machine	Hamilton	ERJ170/175/ 190/195	Worn Support
1001244-1/-2	Shims	1000700-x	Air Cycle Machine	Hamilton	ERJ170/175/ 190/195	Alternate Repair Process
3504927-1	Heater Assy.	3505920-x 3505854-x	Air Driven Unit	Honeywell	B-777-200	Worn Insulation
810167-4	Turbine Shaft	1380209-x	Air Cycle Machine	Hamilton	A380	Damaged Shaft

NORTHEAST AERO DER APPROVED IN-HOUSE REPAIRS

REPAIR P/N	REPAIR Description	NHA P/N	NHA Description	OEM	A/C Application	Scope of Repair
1001243-1/-2	Shims	1000700-x	Air Cycle Machine	Hamilton	ERJ170/175/ 190/195	Alternate Repair Process
3177070-1	Solenoid	3215394-x 3505920-x	777 ADU Mod Valve	Honeywell	B-777-200	Damaged Connector
3455-71	Gasket	1263A0000-x	Air Cycle Machine	Liebherr	A319,A320,A 321	Leaking Duct
1001245-1/-2	Shims	1000700-x	Air Cycle Machine	Hamilton	ERJ170/175/ 190/195	Alternate Repair Process
975483-1/-2	Valve Body	979186-1	Shutoff Valve	Honeywell	B747-200B, CF6-50E2	Bearing Bores
3170678-4	Valve Body	3291172-3	Shutoff Valve	Honeywell	B767-200/- 300, CF6-80	Damaged body
1001237-2	Ring – Fan Rotor	1000700-x	Air Cycle Machine	Hamilton	ERJ170/175/ 190/195	Alternate Repair Process
1001238-1	Nut - Balancing	1000700-x	Air Cycle Machine	Hamilton	ERJ170/175/ 190/195	Alternate Repair Process
3170470-2	Torque Motor	396430-x 396436-x 396462-x	Valve Electromagnetic Control	Honeywell	B767-300/ -200	Damaged Connector
810370-1	Valve Housing	810214-1/-2	Condenser Low Limit Valve	Hamilton	B777-200/ -300	Damaged Flange Area
3179313-1	Bushing Sleeve	3215302-4/-5	High Pressure Shutoff/Pressure Regulating Shutoff Valve	Honeywell	B777-200/ -300	Worn Bushings